

4 ALBERT EMBANKMENT
LONDON SE1 7SR
Telephone: +44 (0)20 7735 7611 Fax: +44 (0)20 7587 3210

MSC.6/Circ.10
14 April 2011

AIS DISCREPANCY REPORTS

January to March 2011 (Quarterly Report)

1 The Maritime Safety Committee, at its eighty-third session (MSC 83/28, paragraph 4.34) in October 2007, requested Member Governments and organizations with consultative status to submit to the Organization details of ships entitled to fly their flag operating either without AIS or with AIS incorrectly configured. Such details should include, where possible, ship name, IMO number, call sign, date, position (latitude and longitude), details of the anomaly and promulgate such information by means of an MSC circular on a periodical basis.

2 The Secretariat continues to receive monthly AIS discrepancy reports on vessels found to be transmitting incorrect AIS data. Analysis of the information shows that in the majority of cases the errors relate to the transmission of wrong IMO number, MMSI (Maritime Mobile Service Identity) and Call sign and name for a particular ship. These information items relate to fixed or static information, which is entered into the AIS on installation and need only be changed if the ship changes its name or undergoes a major conversion from one ship type to another.

3 Member Governments and international organizations are invited to note the information provided in the monthly AIS discrepancy reports for the period January to March 2011, as set out in the annex, and bring them to the attention of all parties concerned.

ANNEX

AIS DISCREPANCY REPORTS – JANUARY TO MARCH 2011

AIS DISCREPANCY REPORT - JANUARY 2011						
Name	IMO	Callsign	Date	Position	AIS Anomaly	Comments
CAPTIN SALIM	6812845	xutb8	07-Jan-11	4141N 03213E	ERRONEOUS	IMO and MMSI were rearranged in system
GULF STAR	7106994	4LZT	07-Jan-11	3621N 02835E	ERRONEOUS	Vessel tx incorrect Callsign and Name
ERKE	7014581	XUFAL	07-Jan-11	4100N 03944E	ERRONEOUS	Transmitting incorrect name MMSI and Callsign
EL PUMA GRANDE	7200180	WU960	10-Jan-11	3438N 03301E	ERRONEOUS	MMSI IMO and Callsign reported wrong from tug
NIKITI	7531187	4LJL2	11-Jan-11	4103N 02902E	NAME/CALLSIGN ERROR	Name and Callsign reported incorrect. Sufficient information in database
ALEJANDRO JOSE	9255361	EBJU	11-Jan-11	3517N 0025E	CALLSIGN ERROR	Reported Callsign is incorrect
ANDREY UPIT	7832804	URRR	14-Jan-11	413515N 0285146E	NAME ERROR	Transmitting wrong name ANDREJS UPITS
ANTEOS	9223681	5BMT2	18-Jan-11	3618N 02518E	NAME ERROR	Showing as AHT ANTEOS on AIS
BELLA STELLA	1003059	SY7947	20-Jan-11	375550N 0234100E	NAME/CALLSIGN ERROR	Vessel transmitting incorrect data
SECONDA	7350090	IKZX	21-Jan-11	441555N 0082655E	NAME ERROR	Vessel transmitting OLD NAME
DUYDEN 2	7525592	TCON4	28-Jan-11	4057N 02853E	IMO ERROR	Vessel is transmitting wrong IMO number 6477016
ANNEZOULA	8890231	SX4300	29-Jan-11	3752N 02334E	NAME ERROR	Vessel is transmitting a wrong name of ANEZOYLA

AIS DISCREPANCY REPORT - FEBRUARY 2011

Name	IMO	Callsign	Date	Position	AIS Anomaly	Comments
TROPICAL MORN	8408870	C6FR7	02-Feb-11	3608N 00522W	NAME ERROR	Transmitting incorrect name of Tropical Reefer
ANTAKYA	7364338	TCA09	03-Feb-11	4061N 029437E	IMO ERROR	Vessel is transmitting incorrect IMO number 736433800
EXPRESS K.	7637319	ERLA	04-Feb-11	4117N 03620E	MMSI ERROR	Transmitting incorrect MMSI 214181201
AMILCAR	9207998	TSAM	05-Feb-11	4348N 00914E	CALLSIGN ERROR	Transmitting incorrect Callsign of TSNA
MACUBA	9163984	V2PQ6	05-Feb-11	3610N 00522W	CALLSIGN ERROR	Transmitting incorrect Callsign of V2FJ7
LADY MALAKEH	7026558	5IM347	05-Feb-11	3715N 02736E	MMSI ERROR	Transmitting old MMSI number of 667099000 instead of new one 677024700 (Tanzania flag)
SISMAISMA	9320386	SWSP	06-Feb-11	3631N 01402E	CALLSIGN ERROR	Transmitting incorrect Callsign of IM.
SWAN ARROW	8512970	C6TK9	07-Feb-11	3659N 00340E	CALLSIGN ERROR	Transmitting incorrect Callsign of C6TU9
ISLA DE LOS VOLCANES	7529885	EEDD	07-Feb-11	3641N 00424W	IMO ERROR	Transmitting incorrect IMO number 7529855
CEMENMAR DOS	7110000	EGAG	07-Feb-11	3931N 00017E	IMO ERROR	Transmitting incorrect IMO number 71110000
CAP CROISSETTE	7708883	FPBG	07-Feb-11	4306N 00552E	CALLSIGN ERROR	Transmitting incorrect Callsign of F13000
VB PROVENCE	9032123	FQRZ	07-Feb-11	4323N 00459E	CALLSIGN ERROR	Transmitting incorrect IMO of FQRS
SIEM LOUISA	9355977	LAIY	07-Feb-11	4113N 03910E	CALLSIGN ERROR	Transmitting incorrect Callsign of LAIY3
NOBLE STAR	7529914	KRPP	08-Feb-11	3531N 02543E	CALLSIGN ERROR	Transmitting incorrect Callsign of KRRP
JIA FOISON	9583603	VRGQ8	08-Feb-11	3554N 00532W	MMSI ERROR	Transmitting incorrect MMSI of 477925700 corresponding to MV Jia Run
VIKTOR LEKAREV	8421896	URKT	08-Feb-11	4620N 03039E	NAME ERROR	Transmitting a uncomplete name of V LEKAREV
BOGATIR	8935988	UIHIQ	09-Feb-11	4620N 03038E	IMO ERROR	Vessel is not transmitting its IMO
NIRINT STAR	9134701	JELXA8	14-Feb-11	3726N 02456E	NAME ERROR	Transmitting old name of Cape Spear
KAPTAN ERGUN	9366445	V7OQ6	14-Feb-11	3742N 02630E	CALLSIGN ERROR	Transmitting incorrect Callsign of TCSN4
BELMOPAN	7361568	V3XL	17-Feb-11	3957N 01900E	IMO ERROR	Transmitting incorrect IMO number 7631568
LUCKY ARROW	7805370	HPXX	17-Feb-11	3616N 02315E	AIS DATA FIELDS ERRONEOUS	Transmitting incoherent data
SEA ENERGY	8124955	3FLY6	22-Feb-11	3836N 02544E	MMSI ERROR	The vessel instead of the correct MMSI number -> 357532000, is showing : 375532000 .

AIS DISCREPANCY REPORT - MARCH 2011

Name	IMO	Callsign	Date	Position	AIS Anomaly	Comments
CAPTAIN MOHAMED K	7126360	4LRC	05-Mar-11	4153N 03055E	Name Error	Transmitting incorrect name Ashrat
DIVA	8863317	V4MF	12-Mar-11	4204N 02917E	Callsign Error	Transmitting incorrect Callsign of V4MR
IRO	9022398	SX8784	13-Mar-11	3646N 02708E	Callsign Error	Transmitting incorrect Callsign of 8747
ANGORA	8502183	9HBM6	13-Mar-11	3606N 00411W	No AIS/ AIS Off	
ARHON	7413921	SY9480	14-Mar-11	3642N 00425W	IMO Error	509284992