



4 ALBERT EMBANKMENT
LONDON SE1 7SR
Telephone: +44 (0)20 7735 7611 Fax: +44 (0)20 7587 3210

Ref. T2-OSS/1.5

MSC.6/Circ.7
1 July 2010

AIS DISCREPANCY REPORTS

April to June 2010 (Quarterly report)

1 The Maritime Safety Committee, at its eighty-third session (MSC 83/28, paragraph 4.34) in October 2007, requested Member Governments and organizations with consultative status to submit to the Organization details of ships entitled to fly their flag operating either without AIS or with AIS incorrectly configured. Such details should include, where possible, ship name, IMO number, call sign, date, position (latitude and longitude), details of the anomaly and promulgate such information by means of an MSC circular on a periodical basis.

2 The Secretariat continues to receive monthly AIS discrepancy reports on vessels found to be transmitting incorrect AIS data. Analysis of the information shows that in the majority of cases the errors relate to the transmission of wrong IMO number, MMSI (Maritime Mobile Service Identity) and Call sign and name for a particular ship. These information items relate to fixed or static information, which is entered into the AIS on installation and need only be changed if the ship changes its name or undergoes a major conversion from one ship type to another.

3 Member Governments and international organizations are invited to note the information provided in the monthly AIS discrepancy reports for the period April to June 2010, as set out in the annex, and bring them to the attention of all parties concerned.

ANNEX

AIS DISCREPANCY REPORTS – APRIL TO JUNE 2010

AIS DISCREPANCY REPORT - APRIL 2010

Name	IMO	Callsign	Date	Position	AIS Anomaly	Comments
Rose	7234765	341583000	02-Apr-10	3228N 03335E	ERRONEOUS	Vessel is transmitting incorrect MMSI 445660000 and Callsign HMV56
Seine	7726847	PBAI	03-Apr-10	311036N 0295217E	IMO ERROR	Transmitting incorrect IMO number 7726874
LIONWIND	1002720	GCZF	03-Apr-10	433254N 0070058E	IMO ERROR	Transmitting incorrect IMO number 703395
FORMENTERA JET	8615253	EHCR	03-Apr-10	385439N 0012607E	IMO ERROR	Transmitting incorrect IMO number 7922851
FM3	7018331	5IM250	04-Apr-10	342833N 0354929E	NAME ERROR	Transmitting incorrect Name of Boss
BOL	8736344	9AA5700	04-Apr-10	450754N 0141437E	IMO ERROR	Not transmitting IMO number
WATERWAY	9143594	J8B3859	04-Apr-10	390256N 0200529E	CALLSIGN ERROR	Transmitting incorrect Callsign of J8B385
V CENTENARIO	7812012	EHXT	05-Apr-10	260633N 0150956W	IMO ERROR	Transmitting incorrect IMO number 6763436
Allure	1004895	V7HS6	05-Apr-10	374047N 0245601E	IMO ERROR	Transmitting incorrect IMO number 70120
GRAND CHAMPION	9340570	3EOR3	06-Apr-10	385716N 0004030E	IMO ERROR	Transmitting incorrect IMO number 4119571
ALTUG1		TC3758	06-Apr-10	361156N 0293827E	MMSI ERROR	This Tug is using a MMSI code assigned to Meander Express (IMO number 9452426)
Montkaj	1000021	ZCCB8	06-Apr-10	433513N 0070750E	MMSI ERROR	Both this vessel and the Car Carrier SALVIA ACE are assigned MMSI 319904000
Sicilia	9430935	A8PF5	06-Apr-10	384709N 1192348E	MMSI ERROR	This vessel and Reecon Eagle are assigned the same MMSI 636091542 and Callsign A8PG5
Charlotta	9064190	A8LA6	06-Apr-10	302717N 0150914W	MMSI ERROR	Vessel is transmitting incorrect MMSI of 63609232
Volcan de Tahiche	7615323	3EGB	06-Apr-10	280824N 0152539W	IMO ERROR	Transmitting incorrect IMO number 75125323
Razende Bol	8434166	PFSD	07-Apr-10	411841N 0020914E	IMO ERROR	Transmitting incorrect IMO number 34383
V Centenario	7812012	EHXT	07-Apr-10	345648N 0084333W	IMO ERROR	Transmitting incorrect IMO number 6763436
TIGRE D'OR	1006532	ZCFB3	08-Apr-10	393335N 0023744E	AIS DATA FIELDS ERRONEOUS	Transmitting incorrect name and IMO number (TIGRUDOR and IMO number 2055108)
Karl Leonhardt	7352464	9HHU6	10-Apr-10	4303N 01500E	NAME ERROR	Transmitting incorrect name of "MV Karl"
Wehr Oste	9252993	V7DY4	14-Apr-10	3559N 00523w	NO AIS/ AIS OFF	Not showing AIS
Lucija	9114141	V7FC8	15-Apr-10	095839N 0151904W	NO AIS/ AIS OFF	Vessel not showing AIS. Last transmission received on 7th March
ALHOUTYAM ASHDOD	-----	-----	16-Apr-10	314937N 0343914E	ERRONEOUS	Not showing IMO and call sign number
AUTUMN WAVE	9038335	C6LF9	16-Apr-10	4330N 01627E	ERRONEOUS	Transmitting AAAAAAAAAA in name field
Bishu Highway	9409340	7JFK	16-Apr-10	3146N 03152E	IMO ERROR	Transmitting incorrect IMO number 9961626
JPO GEMINI	9294020	A8VF7	17-Apr-10	3557N 00564W	IMO ERROR	Transmitting incorrect IMO number 91995
URGULL	9858766	HQWX4	22-Apr-10	3539N 00851W	IMO ERROR	Transmitting incorrect IMO number 9858766
INDIGO	1006312	V71A6	25-Apr-10	364459N 0285616E	MMSI ERROR	Transmitting incorrect MMSI of 319318000
Gramosti	8502200	4LGX2	26-Apr-10	440913N 0284016E	IMO ERROR	Transmitting incorrect IMO number 850200
BISHU HIGHWAY	9409340	9409340	26-Apr-10	3630N 01331E	IMO ERROR	Transmitting incorrect IMO number 9961626 and incorrect MMSI of 432668775
HAI GONG YOU 302	9148465	BCGG	27-Apr-10	2438N 01637W	IMO ERROR	Transmitting incorrect IMO number 10197041
Svyatoy Pavel	7397531	UCQS	29-Apr-10	331011N 0120700E	NO AIS/ AIS OFF	Not transmitting AIS

AIS DISCREPANCY REPORT - MAY 2010

Name	IMO	Callsign	Date	Position	AIS Anomaly	Comments
CHARLOTTA	9064190	A8LA6	08-May-10	354105N 0043408W	MMSI ERROR	Transmitting incorrect MMSI of 636091232
AFAMIA SUN	7412575	V4KR	08-May-10	193731N 0371653E	MMSI ERROR	Transmitting MMSI belonging to another vessel (214180920)
ZANADU	8728995	SY8019	08-May-10	375739N 0233423E	IMO ERROR	Transmitting incorrect IMO number 87288995
Al Sadd	9397341	V7QG9	10-May-10	3557N00539E	NO AIS/ AIS OFF	Not transmitting AIS
Charlotta	9064190	A8LA6	14-May-10	3605N 00514W	MMSI ERROR	Vessel is transmitting incorrect MMSI of 636091232
NELSON	8009416	J8US9	14-May-10	3558N 00522E	NO AIS/ AIS OFF	Not transmitting AIS
MOBY FANTASY	7387706	ICFA	20-May-10	4240N 01007E	IMO ERROR	Transmitting incorrect IMO number 4241978
VOLCAN DE TAHICHE	7615323	3EGB	25-May-10	280842N 0152539W	MMSI/IMO ERROR	Correct MMSI 355346000 error 355364000; Callsign error 7515323
TERRIER	8018168	LAKA4	28-May-10	353356N 0173453E	CALLSIGN ERROR	The vessel is showing a incorrect call sign which is: LAKAR, while the correct one is LAKA4
TERRIER	8018168	LAKA4	28-May-10	351501N 0184423E	CALLSIGN ERROR	Transmitting incorrect Callsign of LAKAR
Ability of London	1008516	MLKK5	30-May-10	393358N 0023830E	NAME ERROR	Ability
Agiantonis	6711493	SV284O	30-May-10	353318N 0242133E	CALLSIGN ERROR	SW-2840
AYDER	7904920	V3OM4	30-May-10	413113N 0364950E	MMSI ERROR	Error 371191000, the correct MMSI 312915000
SIERRA ROMEO	8738744	9HA2191	30-May-10	410147N 0093238	IMO ERROR	Transmitting incorrect IMO number 12256

AIS DISCREPANCY REPORT - JUNE 2010

Name	IMO	Callsign	Date	Position	AIS Anomaly	Comments
KERIR 4	8220034	SSCH	03-Jun-10	310458N 0293945E	NAME ERROR	Transmitting garbled name and incorrect IMO number 7171458
Privilege	8943533	5VAL2	03-Jun-10	375700N 0233223E	MMSI ERROR	Transmitting incorrect MMSI of 691089000
ELIN ARTEMIS	9301653	SVAB	03-Jun-10	380124N 0233127E	CALLSIGN ERROR	Transmitting incorrect Callsign of SVBA8
ZAKAMSK	8951413	UEMK	03-Jun-10	4058N 02855E	MMSI ERROR	Vessel has been transmitting Comoros registration since 04 Nov 09. No documentation found
JOALMI	8902450	P3ZU3	04-Jun-10	3757N 00004E	CALLSIGN ERROR	Transmitting incorrect Callsign of P3UZ3
AREL-2	9068299	TCBF5	04-Jun-10	392537N 0261943E	IMO ERROR	Transmitting incorrect IMO number 3534492
SALPERTON	1011393	ZCYN4	04-Jun-10	4011N 00535E	IMO ERROR	Transmitting incorrect IMO number 101133
Sierra Romeo	8738744	9HA2191	07-Jun-10	410149N 0093237E	IMO ERROR	Transmitting incorrect IMO number 12256
INEVITABLE	1002782	ZHBX8	07-Jun-10	343843N 0330102E	MMSI ERROR	Transmitting incorrect MMSI of 1193046
PRIVATE LIVES	1007861	ZCIN8	07-Jun-10	421130N 0184540E	IMO ERROR	Transmitting incorrect IMO number 2056437
TORINO	9398321	2BZH7	07-Jun-10	275347N 0334109E	CALLSIGN ERROR	Transmitting incorrect Callsign of BZH7
KORMEL	9519614	TCNY2	08-Jun-10	411412N 0312405E	CALLSIGN ERROR	Transmitting incorrect Callsign of TCYN2
SONGA SATURN	8109589	9VKP6	09-Jun-10	354814N 0143236E	CALLSIGN ERROR	Transmitting incorrect Callsign of 9KVP6
MERYAM.S	7405091	5IM325	13-Jun-10	353050N 0354541E	CALLSIGN ERROR	Transmitting Callsign 51M325
ASMARA	9170353	ILGU	13-Jun-10	403827N 0175628E	IMO ERROR	9170350
VOLCAN DE TAHICHE	7615323	3EGB	13-Jun-10	280842N 0152539W	IMO ERROR	Transmitting IMO number error 7515323
VOLCAN DE TAHICHE	7615323	3EGB	16-Jun-10	364804N 0003202E	IMO ERROR	Transmitting incorrect IMO number 7515323
Asvira	9359210	9HMW9	16-Jun-10	3625N 01326		
ASVIRA	9359210	9HMW9	16-Jun-10	3625N 01326E	IMO ERROR	Transmitting incorrect name Asviba and incorrect IMO number 10407786
HANSEATIC SCOUT	9229130	V2BM2	18-Jun-10	402556N 0264559E	NAME ERROR	Transmitting name error PJJJC SCOUT
GB ADRIATIC	8022602	ERIB	19-Jun-10	360312N 0285310E	NAME ERROR	Transmitting name error ADRIATICA
TOR HUMBRIA	7430723	LAWO5	19-Jun-10	385112N 0265440E	NAME ERROR	Transmitting name error HUMBRIA
AL KORTOUBI	8406303	CNCP	20-Jun-10	3559N 00457W	AIS DATA FIELDS ERRONEOUS	Transmitting incorrect name of USTICA and Callsign 3exe8
Brasal Supporter	6607460	HO3795	21-Jun-10	3138N 03431E	MMSI/CALLSIGN ERROR	Brasal Supporter and Centum Chemist (IMO number 9355020) are using the same MMSI of 371756000
KAPITAN BOGOMOLOV	8607402	UCUE	26-Jun-10	280731N 0152417W	IMO ERROR	Transmitting IMO number 9655978
Bow Star	9197296	S6BK3	29-Jun-10	331501N 0262745E	IMO ERROR	Transmitting incorrect IMO number 9197269
TINTOMARA	9234599	A8AR7	30-Jun-10	3750N 00833E	IMO ERROR	Transmitting incorrect IMO number 9234559
ELYSSA	9208007	TSEL	30-Jun-10	4219N 00551E	CALLSIGN ERROR	Transmitting incorrect Callsign of TSNB